


## STRAIGHT ADAPTORS

### G-T

JIC MALE X ORFS FEMALE

JIC MALE X ORFS FEMALE SWIVEL NUT STRAIGHT



Part Number	JIC Male Thread (A)	ORFS Female Thread (B)	O/A (mm)	L1 (mm)	L2 (mm)	Hex A/F - CH1 (mm)	Hex A/F - CH2 (mm)	PN (bar)
G-T-0709	7/16-20	9/16-18	32	10	14	17	17	350
G-T-0909	9/16-18	9/16-18	32	14	22	22	17	350
G-T-0911	9/16-18	11/16-16	27	14	22	22	21	350
G-T-1211	3/4-16	11/16-16	51.5	16.7	27	22.2	25.4	310
G-T-1213	3/4-16	13/16-16	30	17	24	24	27	310
G-T-1413	7/8-14	13/16-16	58.6	19.3	31.3	25	27	240
G-T-1416	7/8-14	1-14	65	19.3	38.1	27	28.6	240
G-T-1716	1.1/16-12	1-14	63.4	21.9	32.5	30	32	240
G-T-1719	1.1/16-12	1.3/16-12	41	22	36	36	37.1	240
G-T-2119	1.5/16-12	1.3/16-12	71.7	23.1	38.1	37.8	37.1	210
G-T-2123	1.5/16-12	1.7/16-12	77	23.1	44.8	38.1	41.3	210
G-T-2623	1.5/8-12	1.7/16-12	79.5	24.3	43.5	42.9	47.6	170
G-T-2627	1.5/8-12	1.11/16-12	79.5	24.3	43.5	42.9	47.6	170